

09/992, 500.


COFC

DOCKET NO.: P04950

PATENT

CLIENT NO.: NATI15-04950

Customer No.: 23990



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Certificate

FEB 16 2006

of Correction

re U.S. Patent No. : 6,911,868 B1

Inventor(s) : Ravi Kumar DVJ

Issued : June 28, 2005

Title : PHASE-LOCKED LOOP FREQUENCY SYNTHESIZER USING
AUTOMATIC LOOP CONTROL AND METHOD OF OPERATION

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF MAILING BY FIRST CLASS MAIL

Sir:

The undersigned hereby certifies that the following documents:

1. Request for Certificate of Correction (in duplicate);
2. Certificate of Correction (in duplicate); and
3. A postcard receipt

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on Feb 8, 2006.

Date: Feb 8, 2006

Kathy Hamilton
Mailer

Date: Jan 27, 2006

William A. Munck
William A. Munck
Reg. No. 39,308

P.O. Drawer 800889
Dallas, Texas 75380
Phone: (972) 628-3600
Fax: (972) 628-3616
E-mail: wmunck@davismunck.com

FEB 16 2006

DOCKET NO.: P04950
CLIENT NO.: NATI15-04950
Customer No.: 23990

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No. : 6,911,868 B1
Inventor(s) : Ravi Kumar DVJ
Issued : June 28, 2005
Title : PHASE-LOCKED LOOP FREQUENCY SYNTHESIZER USING
AUTOMATIC LOOP CONTROL AND METHOD OF
OPERATION

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

FEB 16 2006

Respectfully submitted,

DAVIS MUNCK, P.C.

Date:

Jan 27, 2006



William A. Munck

Registration No. 39,308

P.O. Drawer 800889
Dallas, Texas 75380
Telephone: (972) 628-3600
Facsimile: (972) 628-3616
E-mail: wmunck@davismunck.com

FEB 16 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,911,868 B1
DATED : June 28, 2005
INVENTOR(S) : Ravi Kumar DVJ

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 10, delete "concurrently herewith" and replace with --November 6, 2001--;

Column 1, line 13, delete "concurrently herewith" and replace with --November 6, 2001--;

Column 4, line 24, delete "is";

Column 6, line 48, delete " $1 \leq M \leq 4$ $5 \leq M \leq 9$ $M \leq 16$ " and replace with -- $1 \leq M \leq 4$ $5 \leq M \leq 8$ $9 \leq M \leq 16$ --.

MAILING ADDRESS OF SENDER:

Docket Clerk
P.O. Drawer 800889
Dallas, Texas 75380

PATENT NO. 6,911,868 B1

No. of additional copies

 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

FEB 16 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,911,868 B1
DATED : June 28, 2005
INVENTOR(S) : Ravi Kumar DVJ

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 10, delete "concurrently herewith" and replace with --November 6, 2001--;

Column 1, line 13, delete "concurrently herewith" and replace with --November 6, 2001--;

Column 4, line 24, delete "is";

Column 6, line 48, delete " $1 \leq M \leq 4$ $5 \leq M \leq 9 \leq M \leq 16$ " and replace with -- $1 \leq M \leq 4$ $5 \leq M \leq 8$ $9 \leq M \leq 16$ --.

MAILING ADDRESS OF SENDER:

Docket Clerk
P.O. Drawer 800889
Dallas, Texas 75380

PATENT NO. 6,911,868 B1

No. of additional copies

 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

FEB 16 2006